


Visual Health Check

Name	James Middlebrooke	Mileage	21030	Date	27 Aug 2010
Vehicle	BMW, 1 Series	Registration	KG58GYI	MOT Due	11 Aug 2011
Telephone	01216042000	Job Number	14698C	Service Due	11 Aug 2011
Mobile	07811185000	Vehicle Identity		Timing Belt Due	11 Aug 2013

As part of this visual appraisal, these areas of your vehicle were inspected:



Red Items: These items require your urgent attention.

Category	Description	Recheck	Auth	Fitted Price
Electrical	Electrical, Brake Lights, Not working, Advise Tech Note: Intermittent fault		✓	£52.88
Mechanical	Mechanical, Engine oil, Low, Advise Advisor/Parts Note: In stock		✓	£18.22

Amber Items These items will require your attention in the near future.

Category	Description	Recheck	Auth	Fitted Price
Brakes	Brakes, Brake Pads, Front, Worn 60-70%, Advise Tech Note: Slightly lipped condition Advisor/Parts Note: Stock arriving PM		✓	£193.88
Mechanical	Mechanical, Pollen filter, Contaminated, Replace Advisor/Parts Note: Free Fitting Part Numbers: #22FHG POLL, #453FD POLL		✓	£14.10

Authorised	Identified
£279.08	£279.08

Additional Notes:

Front tyres 47% worn. Call back in 6 months for a complimentary Vehicle Health Check.

Tyre Report					Body Report		Healthcheck Approval	
		Left	Middle	Right	Wear			
Nearside Front	Tyre	5mm	5mm	5mm	47%	○ Chip □ Scratch	Technician:	
Offside Front	Tyre	5mm	5mm	5mm	47%	● Corrosion ■ Crack ▲ Dent	Service Contact:	David Mason
Offside Rear	Tyre	7mm	7mm	7mm	16%		Customer:	The details above have been brought to my attention.
Nearside Rear	Tyre	7mm	7mm	7mm	16%			
Spare	Sealant	0mm	0mm	0mm				
Front		195/30 R18 75VR Yokohama						
Rear		195/30 R18 75VR Yokohama						